




## Sasib 5000 Label unit update



## Reduce the frequency of label jams with a label unit update



Issue

- Label jam caused by friction between the label and label guides
- Incorrect position of the label at the turret location

Consequences •

- Loss of production
- Down time
- Damaged parcels/cigarettes

Solution

- Label guide rollers and label positioning drive
- Label guides supplied with rollers for less friction during transport
- Label positioning at turret location for correct position of the label before transfer to turret

Advantages

- Less label jams
- Higher quality of parcel

Scope

Complete kit to upgrade existing label unit

Time required

- Approx. machine down time: 8 hours (1 working day)
- Total mechanical hours: 16 hours
- Total electrical hours: 0 hours

Guarantee

One year guarantee

Suitable for all Sasib 5000

