







## Accurately detect stamp application problems with a missing stamp camera upgrade



Issue Consequences Solution Advantages Incorrectly applied stamps

Consequences • Missing stamps on product

Missing stamp camera

 Upgrade your stamper to include camera stamp detection. Your pack and stamp may contain incompatible colours for typical detection.
With the addition of this camera precise colour tuning is possible

Scope Time required Missing stamp camera attachment

Approx. machine down time: 26 hours (0 working days)

Total mechanical hours: 8 hours

Total electrical hours: 8 hours

Guarantee • One year guarantee

Suitable for all stampers

