

Retrofit to new chamber for 7 to 9mm channel width



## ITM5000/Mark 9 Complete suction chamber with nylon tape




## Improve rod handling and minimise down time with a complete suction kit with nylon tape

Solution

Advantages

Time required



Uneven rod handling

Increased incidence of loose ends

Difficult adjustment and maintenance

Consequences • Down time for maintenance

Narrow range of cigarette weight

Complete new suction rod conveyor available for 7 to 9mm channel width

Reduced incidence of loose ends

Improved cigarette quality

Reduced maintenance requirements

Wider range of cigarette weight

Scope • Exchange of complete suction chamber

Approx. machine down time: 24 hours (3 working days)

Total mechanical hours: 40 hours

Total electrical hours: 8 hours

GuaranteeOne year guaranteeOther optionsWear-optimised con

 Wear-optimised components made of carbide or specially coated materials

New large fan upgrade is advised

Suitable for ITM5000 and Mark 9

