






Improve stem separation and cigarette quality with a pivotable upper blowing chamber



Issue

Stem separation inadequate for tobaccos containing a high proportion of stems

- Consequences Stem content in cigarette is too high
 - Stem causes holes in the cigarette paper

Solution

- Retrofit kit to convert to a pivotable upper blowing chamber
- With adjustable stem detector
- With intensified air stream to end of wall

Advantages

Improved cigarette quality

Scope

Replacement of complete unit

Time required

- Approx. machine down time: 24 hours (3 working days)
- Total mechanical hours: 32 hours

Guarantee

One year guarantee

Other options

Improved stem separation

Suitable for ITM8000/Protos 80

