





Improve cigarette quality and reduce the incidence of loose ends with a suction rod conveyor SWORD type

Solution



Uneven rod formation Issue

Increased incidence of loose ends

Difficult adjustment and maintenance

Consequences • Loss of production

Down time for maintenance

Fluctuation of cigarette weight

New suction rod conveyor available for 7 to 9mm channel width Improved performance Advantages

Reduced incidence of loose ends

Improved cigarette quality

Reduced maintenance

 Retrofit to new suction rod conveyor for 7 to 9mm channel width Scope

• Approx. machine down time: 24 hours (3 working days) Time required

Total mechanical hours: 40 hours

Guarantee One year guarantee

Other options Wear-optimised components made of carbide or specially coated material

Suitable for ITM8000/Protos 80

