


GD CK Counter pusher



Improve material alignment quality with a counter pusher upgrade



Issue

Consequences • Quality issue

Solution

Scope

Advantages

Guarantee

Time required

Poor material alignment around the parcel

Integration of a counter pusher for the first horizontal packet transfer

Material is held between packets and pusher to keep the alignment through the transfer

Improved quality

• Integration of a counter pusher for the first horizontal packet transfer

• Approx. machine down time: 40 hours (5 working days)

Total mechanical hours: 50 hours

Total electrical hours: 0 hours

One year guarantee

Suitable for all GD CK

