

GD 4350

Pneumatic packet hopper


Replacement of the refill packet hopper with a pneumatic hopper







Improve packet quality through reduced abrasion with a pneumatic packet hopper



Issue

 Quality issues with film appearance caused by abrasion between packets within the hopper and packets in the exit wheel

Consequences Solution

- Consequences Non-conforming product
 - Integration of pneumatic hopper
 - Pneumatic hopper creates space between the last packet in the hopper and the packets transferred to the exit wheel

Advantages Scope

Time required

Quality improvement

- Integration of pneumatic hopper and packet lifter
- Approx. machine down time: 10 hours
- Total mechanical hours: 16 hours
- Total electrical hours: 16 hours

Guarantee

One year guarantee

Suitable for all GD 4350

