

www.itmgroup.eu





## Improve packet film quality with a parcel shrink tunnel upgrade



Issue

Advantages

Time required

Scope

Solution

- Quality issues with film appearance
- Consequences Non-conforming product
  - Integration of top/bottom heated plates to utilise the properties of heat sensitive films
  - Retractable top/bottom heater and opening front for ease of access
  - Air jets to cool chamber during machine stoppage
  - Quality improvement
  - Integration of top/bottom heated plates
  - Approx. machine down time: 16 hours (2 working days)
  - Total mechanical hours: 24 hours
  - Total electrical hours: 24 hours
- Guarantee One year guarantee

Suitability dependent on vintage of GD CV

