



Leading innovator
for the
**TOBACCO
INDUSTRY**
with a passion to serve

GD X2

8th wheel

8th wheel with packet eject for
non-conforming product



GD X2 8th wheel

Improve packet quality and machine performance with an 8th wheel upgrade



Issue	<ul style="list-style-type: none">• Packet abrasion on the belt system• Unreliable packet transport
Consequences	<ul style="list-style-type: none">• Non-conforming product• Damaged packets• Loss of production• Down time
Solution	<ul style="list-style-type: none">• Removal of the belt system and replacement with wheel transport design• Hardened barrel cam for smoother packet acceleration and deceleration• Accurate packet positioning in rotating pockets
Advantages	<ul style="list-style-type: none">• Improved performance• Improved packet quality• Reduced maintenance
Scope	<ul style="list-style-type: none">• New 7th wheel group, new 8th wheel group
Time required	<ul style="list-style-type: none">• Approx. machine down time: 52 hours• Total mechanical hours: 60 hours• Total electrical hours: 16 hours
Guarantee	<ul style="list-style-type: none">• One year guarantee

Suitable for all GD X2

