

Max-S

Improved inspection drum

Exchange the existing inspection drum for an improved design



Max-S/Max-80 Improved inspection drum



Improve performance and quality with an improved inspection drum



Issue

- Too many rejections of good cigarettes
- Poor leak test
- Risk of quality problems

Consequences • Lower production quality

Solution

 Improve leak test by exchanging the old inspection drum for an improved inspection drum

Advantages

- Less quality risks
- Improved performance

Scope

 Complete exchange of existing inspection drum including controls

Time required

- Approx. machine down time: 24 hours (3 working days)
- Total mechanical hours: 40 hours
- Total electrical hours: 24 hours

Guarantee

One year guarantee

Other options

Can be extended with a loose end scanner upgrade

Suitable for Max-S

