

ITM5000/Mark 9

Large fan unit

New large fan unit with increased vacuum power








Improve cigarette quality with a large fan unit for increased vacuum power in the suction chamber

Solution

Scope

Time required



Uneven rod formation with slim and super-slim sizes

Consequences • Poor cigarette quality

 Retrofit to the large fan unit for increased vacuum power in the suction chamber

Advantages • Improved cigarette quality

• Complete kit to replace the large fan unit and motor (9kW)

Approx. machine down time: 40 hours (5 working days)

Total mechanical hours: 40 hours

Total electrical hours: 16 hours

GuaranteeOne year guaranteeOther optionsRecommended for t

Recommended for the suction chamber with nylon tape upgrade

Suitable for ITM5000 and Mark 9

