

ITM5000/Mark 9

Double paper handling unit (double wrap)


Additional automatic bobbin holder/splicer to supply the second wrap







Improve cigarette quality with an additional bobbin holder/splicer to supply the second wrap



Issue

Spots on the cigarette paper

Poor cigarette quality, especially with special cut rag or with use of flavours

Consequences • Loss of quality

Solution

Advantages

Scope

Time required

An automatic bobbin holder/splicer to supply the extra paper wrap

• Improved cigarette quality

• Complete automatic bobbin changer mounted to the machine

• Approx. machine down time: 40 hours (5 working days)

Total mechanical hours: 60 hours

Total electrical hours: 40 hours

Guarantee

Other options

One year guarantee

• As an alternative we can offer a free standing Ganymede

Suitable for ITM5000 and Mark 9

