





## Improve stem separation with a wider strip extension on the stem chute


Advantages

Guarantee

Time required

Other options

Scope



 Difficulty adjusting stem separation Issue Consequences • Stem level in cigarettes can be to high Solution

Retrofit kit to improve stem separation

Improved housing design

Wider secondary separator

Higher tobacco yield • Replace stem chute

• Approx. machine down time: 8 hours (1 working day)

Total mechanical hours: 16 hours

One year guarantee

Pivotable upper blowing chamber

Suitable for ITM8000/Protos 80

