

Vertical packet elevator and packet transport group



GD4350 Long infeed group



Achieve suitability for an integrated stamper with a long infeed group

Issue

Unable to use integrated stamper

Reliability issues

Quality issues with packet damage

Consequences • Increased down time

Loss of production

Non-conforming product

Solution

Replacement of infeed group with a new unit

Front or rear infeed

Packet elevator to separate packets

Timex belt for packet transportation

Internal overload clutch

Advantages

Improved performance

Suitable for integrated stamper

Reduced down time

Scope

Replacement of infeed group with a new unit including required format and guardings

Time required

• Approx. machine down time: 32 hours (4 working days)

Total mechanical hours: 40 hours

Total electrical hours: 32 hours

Guarantee

One year guarantee

Suitability depending on vintage of GD 4350

