

Max-S

Tipping paper extraction


Add a device for extracting/collecting tipping patches







Improve cigarette quality and reduce production faults with a tipping paper extraction upgrade



Issue

Non applied tipping patches in the machine

Consequences • Poor cigarette quality

Production faults

Machine pollution

Installation of tipping patch extractor

 Non-glued tipping patches (machine start/stop) are extracted/collected from the production area

Advantages

Solution

Improved operation and maintenance

Improved cigarette quality

Reduced cleaning time

Scope

Complete kit

Time required

• Approx. machine down time: 32 hours (4 working days)

Total mechanical hours: 40 hours

Total electrical hours: 16 hours

Guarantee

One year guarantee

Suitable for Max-S

