

## Max-S

## Longer bolts for tipping guide

Support bolts to avoid damaging the needles in the swash plate







## Increase operational ability and decrease down time with longer bolts for the tipping guide



Issue

 Damage to the needles in the needle drum when the tipping guide is being fitted or removed

Consequences •

Down time

Increased maintenance requirements

Solution

Longer bolts for the tipping unit

Advantages

Increased operational ability

Scope

Exchange of existing bolts

Time required

• Approx. machine down time: 2 hours (0.25 working days)

Total mechanical hours: 2 hours

Guarantee

One year guarantee

Suitable for Max-S

