

www.itmgroup.eu





## Reduce foil wrinkles with a post shrink heater upgrade



Issue

Solution

Foil around the parcel may be wrinkled

Consequences • Poor visible quality

Post shrink heater

Heater assembly to shrink the foil so that it will be tight around the parcel

Pneumatic cylinder dislocates the heater during a stop

Advantages Scope

Improved visual quality

 Assembly kit for the post shrink heater to assemble at the outfeed of the CP1

Time required

• Approx. machine down time: 16 hours (2 working days)

Total mechanical hours: 8 hours

Total electrical hours: 24 hours

Guarantee

• One year guarantee

Suitable for ITM rebuild Sasib CP1

