


## **GD X1** Optical cigarette end detection



## Increase the reliability of end detection with an optical cigarette end detection upgrade



Unreliable detection

Damage of cigarettes with pin impact

Consequences • Higher cigarette waste

Higher risk of non-conforming product

Reduced product quality

Loss of production

Solution
Removal of pin mechanism and replacement with optical scanning heads

Scanning for loose ends is adjustable to the required quality level

Scanning for missing cigarette/filter adjustable to different configurations

Advantages • Improved performance

• Improved cigarette quality due to no impact on cigarette ends

Reduced waste

Scope • Optical cigarette end detection group

Approx. machine down time: 24 hours (3 working days)

Total mechanical hours: 32 hours

Total electrical hours: 32 hours

Guarantee • One year guarantee

Suitable for all GD X1

Time required

