





Improve efficiency and minimise maintenance requirements with an improved fan unit



Issue

Not enough vacuum power on the Max-S/Max-80

Consequences • Low production efficiency

Down time for maintenance

Solution

Retrofit for the fan unit

Advantages

• Higher efficiency

Less maintenance requirements

Scope

Complete kit to replace the fan unit and modify the frame if necessary

Time required

• Approx. machine down time: 40 hours (5 working days)

Total mechanical hours: 40 hours

Total electrical hours: 16 hours

Guarantee

One year guarantee

Suitable for Max-S

