





Lower noise levels with a motor noise reduction guard set



 Excessive noise levels Issue Consequences • Impaired operator hearing Solution

Replacement of rear guards

Made from noise-reduction materials

Interlock option Reduced noise

Advantages Scope Time required

• Replacement of rear guards

• Approx. machine down time: 0.5 hours

Total mechanical hours: 0.5 hours

Total electrical hours: 0 hours

Guarantee One year guarantee

Suitable for all GD 4350

