

Max-S

Rack-type turning drum

Exchange the existing turning drum for a rack-type turning drum







Increase operational reliability and service life whilst reducing maintenance requirements with a rack-type turning drum





Issue

The function of the turning drum is impaired

Consequences • Loss of production

Down time

Increased maintenance requirements

Conversion to a rack-type drum which uses a rack

mechanism instead of a barrel

Advantages

Time required

Solution

Scope

Increased operational reliability

Increased service life

Reduced maintenance requirements

Complete exchange of the existing turning drum

• Approx. machine down time:

Max-S: 32 hours (4 working days) Max-80: 16 hours (2 working days)

Total mechanical hours:

Max-S: 32 hours Max-80: 16 hours

Guarantee

One year guarantee

Suitable for Max-S

